

Appendix A

Photo Logs

Facility Siting General Photolog



View to northeast of Lock 7 from Hudson River (07/31/03). Note: Lock 7 connects the Hudson River to the Champlain Canal.



View to south of upstream entrance to Lock 6 (07/31/03). Note that the entrance is via a long and narrow channel paralleling the Hudson River.

Facility Siting General Photolog



View to south of upstream entrance to Lock 5 (07/31/03).



View to south of empty Lock 4 (08/1/03).

Facility Siting General Photolog



View to west of west bank of Hudson River opposite the Bruno/Brickyard/Alonzo site (08/01/03).



Typical Geoprobe activities (10/08/03).

Facility Siting General Photolog



Typical drilling of Geotechnical boreholes (10/07/03).



Typical Steam cleaning of augers (10/01/03).

Facility Siting General Photolog



Typical completed temporary well (10/16/03).



Typical completed temporary well at State of NY/First Rensselaer/Marine Management site (10/16/03).

Facility Siting General Photolog



Typical completed (backfilled) soil boring (10/16/03).



Typical drum storage shed (10/16/03).

Facility Siting General Photolog



Inside of typical drum storage shed (10/15/03).



Typical arrangement of drums inside the storage sheds (10/16/03).

Facility Siting General Photolog



View to north of vandalized drum storage shed at State of NY/First Rensselaer/Marine Management site (11/06/03).

**Facility Siting Site Inspection Photolog
Energy Park**



View to west of center of property – cornfield (07/08/03).



View to north of fill area in center of site (07/08/03).

Facility Siting Site Inspection Photolog Energy Park



View to southwest of Champlain Canal and adjacent Canal Road along southeast side of parcel (07/08/03).



Split-spoon of highly plastic clay, 20- to 22-foot-depth interval from boring EPL-GT02 (09/30/03).

**Facility Siting Site Inspection Photolog
Energy Park**



Contact of silty sand overlying well-graded sand at 5 feet BGS, in split-spoon sample from boring EPL-GT03 (09/30/03).

**Facility Siting Site Inspection Photolog
Old Moreau Dredge Spoils Area**



View downstream of Hudson River shoreline (07/11/03).



View to north of Hudson River shoreline (07/11/03).

**Facility Siting Site Inspection Photolog
Old Moreau Dredge Spoils Area**



View to northeast of former pumphouse channel (07/11/03).



**View to west of Old Moreau (near former paper recycling facility)
from Hudson River (07/31/03).**

**Facility Siting Site Inspection Photolog
Old Moreau Dredge Spoils Area**



View to northwest of Old Moreau from Hudson River (07/31/03).

**Facility Siting Site Inspection Photolog
Georgia Pacific**



View upstream of north end of dock (07/10/03).



View to northwest of former land farm area (07/10/03).

**Facility Siting Site Inspection Photolog
Georgia Pacific**



View to south of two of 11 drums in northwest corner of site (07/10/03).



View to southeast of northernmost railroad spur to the southwest of the former power canal (07/10/03).

**Facility Siting Site Inspection Photolog
Georgia Pacific**



Close-up of black tar-like material from drum in northern drum disposal area (10/09/03).



View of drum containing black tar-like material in northern drum disposal area (10/09/03).

**Facility Siting Site Inspection Photolog
Georgia Pacific**



View to southeast of the Georgia Pacific site from Hudson River, upstream of the Route 4 bridge (07/31/03).



View to southeast of Georgia Pacific site downstream of the Route 4 bridge (07/31/03).

**Facility Siting Site Inspection Photolog
Georgia Pacific**



View to east of Northumberland Dam and Georgia Pacific site shoreline (07/31/03).



View to north shoreline from bulkhead 07/10/03.

**Facility Siting Site Inspection Photolog
Georgia Pacific**



View to north of concrete structure along shoreline, north of bulkhead (07/10/03).



View to north from bulkhead (07/10/03).

**Facility Siting Site Inspection Photolog
Georgia Pacific**



View to south from bulkhead. Note entrance to former power generating canal just north of bulkhead (07/10/03).



View to west of Northumberland Dam from Georgia Pacific site (07/10/03).

**Facility Siting Site Inspection Photolog
Georgia Pacific**



View to west of former power generating canal outfall (07/10/03).

**Facility Siting Site Inspection Photolog
Bruno/Brickyard Associates/Alonzo Site**



View to west of old gravel pit with debris (07/24/03).



View to southeast of railroad tracks (07/24/03).

**Facility Siting Site Inspection Photolog
Bruno/Brickyard Associates/Alonzo Site**



View to south of shoreline (07/24/03).



View to north of Shop building (left) and Office building (right) (07/24/03).

**Facility Siting Site Inspection Photolog
Bruno/Brickyard Associates/Alonzo Site**



View to northwest of former coal storage area (07/24/03).



View to southeast of site from Hudson River (08/01/03).

**Facility Siting Site Inspection Photolog
Bruno/Brickyard Associates/Alonzo Site**



View to west of building destroyed by tornado (near temporary well BBA-GP01) (07/24/03).



View to west of building destroyed by tornado (near surface soil sample BBA-SS04) (07/24/03).

**Facility Siting Site Inspection Photolog
Bruno/Brickyard Associates/Alonzo Site**



View to northwest of ASTs at Brickyard facility near surface soil BBA-SS02 (07/24/03).

**Facility Siting Site Inspection Photolog
NYS Canal Corp**



View to southeast of residences located in southeastern portion of property (07/23/03).



View to south dump located near the east-central portion of property (07/23/03).

**Facility Siting Site Inspection Photolog
NYS Canal Corp**



Split-spoon from boring NCC-GT01 (10/07/03).



**Tires and other debris at surface soil sample location NCC-SS03
(10/02/03).**

**Facility Siting Site Inspection Photolog
NYS Canal Corp**



Debris and waste near surface soil sample location NCC-SS04 (10/02/03).



Material underlying surface soil sample location NCC-SS06 (10/02/03).

**Facility Siting Site Inspection Photolog
NYS Canal Corp**



View to north of drum and other debris near surface soil sample location NCC-SS06 (10/02/03).



View to south of drums, cables, and debris at surface soil sample location NCC-SS07 (10/02/03).

**Facility Siting Site Inspection Photolog
NYS Canal Corp**



View to west of NYS Canal Corp. site from Hudson River (08/01/03).



View to west of southern end of NYS Canal Corp. site from Hudson River (08/01/03).

**Facility Siting Site Inspection Photolog
NYS Canal Corp**



Drums in northern portion of NYS Canal Corp. parcel near surface soil NCC-SS06 (10/02/03).



Dump in northern portion of NYS Canal Corp. parcel near surface soil NCC-SS07 (10/02/03).

**Facility Siting Site Inspection Photolog
State of NY/First Rensselaer/Marine Management**



View to north of log pile with iron spikes in some logs (07/17/03).



View to south of dumping area adjacent to access road bisecting the site (07/17/03).

**Facility Siting Site Inspection Photolog
State of NY/First Rensselaer/Marine Management**



View to north of ash pile along west side of the railroad in the central portion of the site (07/17/03).



Drum near surface soil sample location MM-SS09 (10/08/03).

**Facility Siting Site Inspection Photolog
State of NY/First Rensselaer/Marine Management**



View to south (downstream) of shoreline (07/17/03).



**View to north (upstream) of shoreline from train bridge abutment
(07/17/03).**

**Facility Siting Site Inspection Photolog
State of NY/First Rensselaer/Marine Management**



Fill material in Geoprobe soil sample from MM-GP01 (10/10/03).

**Facility Siting Site Inspection Photolog
OG Real Estate**



View to north of Niagara Mohawk right-of-way on OG Real Estate property (07/22/03).



View to north of Niagara Mohawk power lines from southwest corner of the site (07/22/03).

**Facility Siting Site Inspection Photolog
OG Real Estate**



View to southeast (downstream) of shoreline with riprap breakwall (07/22/03).



View to north of Albany Port from northeast corner of site (07/22/03).

**Facility Siting Site Inspection Photolog
OG Real Estate**



View to north of shoreline from southern portion of site (07/22/03).



View of typical fragmites covering most open areas (07/22/03).